

Q-206



SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via website: www.fleet.ford.com/truckbbas (click "Contact Us")

Toll-free: (877) 840-4338

QVM Bulletin: Q-206

Date: 27 May, 2011

2012 F53/F59 Trailer Brake Controller Connector Relocation

Models Affected: 2012MY and later F53 Motorhome Chassis, 2012 and later F59 Commercial Truck Stripped Chassis

Issue: For 1999 to 2011 chassis, the trailer brake controller connector is located behind the instrument cluster (Figure 1). Access to this connector can be difficult after the instrument panel is installed.





Figure 1 – Trailer Brake Controller Connector – 1999 through 2011

Description: To improve service and customer access, the connector has been relocated on 2012 model year chassis's (effective 7-15-2011). The connector is located on the left hand side of the steering column support (Figure 2). The end-of-frame trailer wiring is carry over and is not affected by this change.



If you have any questions, please contact the Ford Truck Body Builders Advisory Service as shown in the header of this bulletin.