

# Q-317



## SVE BULLETIN

**SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE**

E-Mail via Website: [www.FordBBAS.com](http://www.FordBBAS.com) (click "Contact Us")

Toll-free: (877) 840-4338

QVM BULLETIN: Q-317

DATE: 18/May/2020

### 2021MY E-Series Cutaway Vehicles Equipped With Radio Delete And USB Cable

REVISION	UPDATE	REVISION DATE
	INITIAL RELEASE	


#### MODEL(S) AFFECTED:

2021MY E-Series Cutaway Vehicles Equipped With Radio Prep-Package

#### ISSUE / DESCRIPTION:

When the vehicle is ordered / equipped with the Radio Prep Package from factory, the USB connector and cable have been installed in the instrument panel. The USB port (shown in image below) will be **non-functional**. It is the Intermediate / Final Stage Manufacturer's responsibility to either remove the USB cable, or construct a cap / cover to hide USB port and USB symbol in the instrument panel, or inform the final customer that the USB port is non-functional.

The Intermediate / Final Stage Manufacturer can make the USB port/wiring functional once again by equipping with an aftermarket radio (or equivalent device) if desired.



Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the [Ford Body Builders Advisory Service](#) as shown in the header of this bulletin.